



# Maple Leaf Consulting Inc.

R.R. #1  
Rocky Mountain House, Alberta  
T4T 2A1

(403) 348-3458  
Fax: (403) 845-4775

March 26, 2019

Reference: **MLC-23557**

**CANYON CASING SERVICE LTD.**  
**2-12 Erickson Crescent**  
**Sylvan Lake, Alberta**  
**T4S 1P5**

Attention: **Jeff Dell**

## EQUIPMENT CERTIFICATION

<b>Equipment:</b>	<b>Slip-type Elevator</b>
<b>Manufacturer:</b>	<b>AOT</b>
<b>Model:</b>	<b>HYC</b>
<b>Capacity:</b>	<b>200 Ton</b>
<b>Serial Number:</b>	<b>E55310 28522</b>
<b>Load Test Number:</b>	<b>MLC-20199LT0711</b>
<b>Reference:</b>	<b>CCE H-1</b>

The above elevator was examined in detail on March 26, 2019 at Maple Leaf Consulting's shop. The above elevator was fully disassembled and sandblasted for a C.A.O.D.C. RP-2.0 Level IV inspection. Magnetic particle and/or visual inspections were completed on all accessible areas of the body, door, latch, secondary latch, hinge pin, latch pin, secondary latch pin, and latch spring.

Based on the inspections, it is our opinion that the unit is safe to operate within its rated capacity when used in accordance with the manufacturers' specifications and/or industry standards.

In accordance with C.A.O.D.C. RP-2.0, a certification period of 500 operating days is recommended. Due to the nature of Canyon's business, this **certification is valid for a period of 2 years** or until the unit has been damaged structurally by either handling or operation. Unengineered structural modifications to this unit will void this certification.

<b>PERMIT TO PRACTICE</b> <b>MAPLE LEAF CONSULTING INC.</b>
Signature <u>Everett M. Gusek, P. Eng.</u>
Date <u>March 26, 2019</u>
<b>PERMIT NUMBER: P 7117</b>
The Association of Professional Engineers, Geologists and Geophysicists of Alberta

